Invoice Date: 01/10/2014

Invoice #

16675

Motor Hours: 2408.7 Vin# : 2933 Writer : Marc L Yr/Make : 1988 PETTIBONE Date : 01/30/2008 Model : 360 speedswing unit 16675 : Detroit Motor Phonel Plate : HSL16675 Unit# : 16675 Ext. Miles Phone2

Quantity	Part Number / Tech	Description	Parts	Labor
50.00	BG8F12112	GR BOLTS & WASHERS	25.00	
1.00	OLA-01058-025	VALVE, 2 SPOOL CLOSED CENTER	3,825.62	
2.00	17405	V-BELT GATORBACK	31.12	
1.00	KZ10	HYD FILTER SCHROEDER	38.69	
1.00	T224	FILTER TURBO 2000	125.81	
1.00	P119373	AIR FILTER	22.89	
1.00	P181046	AIR FILTER	33.51	
2.00	P550388	FILTER HYD 10 MICRON	22.90	
1.00	5582	SWITCH TOGGLE	6.21	
4.00	16692	HYRAIL GUARDS	700.00	
2.00	6735	V-BELT	26.36	
1.00	117-4417OU	FILTER OIL GENERATOR	5.58	
1.00	80301	OIL PRESSURE SENDING UNIT	62.51	
1.00	860008184	SERVICE TIRE /FITTINGS	224.80	
13.00	15W40	15W40 MOTOR OIL	36.14	
1.00	1117911	DELCO 12 VOLT ALTERNATOR	225.00	
1.00	57407	TRANSMISSION FILTER	55.39	
1.00	P554073	FILTER COOLANT	11.28	
3.00	G60130-0402	4MP-2FPS	2.88	
2.00	42469	HYD TANK BREATHER	24.96	
1.00	EF-ABC10	FIRE EXTINGUSHER	59.95	
1.00	82305	OIL PRESSURE GAUGE 12V 0-100	59.17	
1.00	D4	ESPAR TRUCK HEATER 12V	2,518.28	
1.00	62641INV	HOSE ASSEMBLIES	195.37	
4.00	432401001200053	24x10Pettibone speed swing whe	3,610.24	
1.00	0218437INV	SEAL KIT	30.32	
1.00	1131INV	SWIVEL SEALS	111.42	
1.00	0218437INV	SEALS CLAM ROTATOR	30.32	
1.00		STARTER 12V	235.00	
1.00	holph-30rp41	PINTLE HOOK	56.92	
1.00	00258470 inv	boarder fee	57.00	
	P550936	PRIMARY FUEL FILTER	5.61	

1.00	1330730	1 1(11/1/1 11(1 4				
*****	************ Thank You *********		We Believe that quality workmanship, will protect your Investment and family.***Thank You for your Business and Come Again!***	your	Labor Parts	22,519.21 27,852.17
					Inspection	0.00
			I hereby authorize you to perform the above repair work inclu		Towing	0.00
			necessary parts and materials set forth. Additional labor, parts materials may be required to repair the vehicle, and further such repair that not be performed until after I have authorized them either in writing the materials.		Sublet	0.00
	Service Recommendations			pairs	Shop Charge	0.00
1	installed at 2408.7hrs ine from america diesel		or verbally. You and your employees are authorized to operate vehicle on streets, highways or elsewhere at my risk for the purpo	the	Subtotal	50,371.38
		test inspection and delivery. It is understood and agreed the refacility is not responsible for any loss or damage to vehicle.		H.S.T.	0.00	
					Amount Paid	0.00
			XReceived By		Total Due	50,371.38

Phonel

Phone2

Invoice Date: 01/10/2014

Ext.

Invoice #

16675

Model

Plate

Miles

: 2933 Yr/Make : 1988 PETTIBONE

: 360 speedswing unit 16675 : HSL16675

Motor Hours: 2408.7 Writer : Marc L Date

: 01/30/2008

Motor : Detroit Unit# : 16675

Quantity	Part Number / Tech	Description	Parts	Labor
1.00	P550928	SECONDARY FUEL FILTER	5.83	
1	P181046	AIR FILTER	29.47	
1.00	P551670	ENGINE OIL FILTER	13.40	
20.00	20	Trans Fluid	62.00	
205.00	AW32	TELLUS OIL 32	504.30	
2.00	P550388	oil filter	26.58	
300.00	AW32	TELLUS OIL 32	609.00	
6.00	ANTIFREEZE	ANTIFREEZE 4 L. JUGS	86.57	
1.00	P532504	FILTER AIR SOFTNERS	31.57	
1.00	P550928	SECONDARY FUEL FILTER	6.85	
1.00	P550936	PRIMARY FUEL FILTER	7.61	
1.00	P551670	ENGINE OIL FILTER	15.52	
1.00	P554073	FILTER TRANSMISSION	13.52	
1.00	P532503	FILTER AIR -PRIMARY	39.52	
2.00	2240-6-8S	FITTING ADAPTER EXT PIPE 37 BL	14.20	
16.00	15W40	15W40 MOTOR OIL	36.32	
1.00	15361	V-BELT GATORBELT	10.80	
1.00	57407	FILTER - TRANSMISSION	54.29	
1.00	15361	V-BELT GATORBACK	10.80	
2.00	15371	V-BELT GATORBACK	21.00	
3.00	1174417	FILTER-SPIN ON OIL	26.85	
1.00	00261014 INV	BROKERAGE -DRIVE SHAFT	32.50	
1.00	00261013 INV	BROKERAGE - PARTS PETTIBONE	32.50	
3.00	10-17-106	LEFT REAR GUARD	828.46	
1.00	33358	FUEL FILTER	6.61	
1.00	00-415-7223	FUEL SUPPLY PUMP	57.30	
1.00	BG8C1-8	BOLT 1"x8" FR 8 HXHD	7.80	
1.00	49060 WIX	HYD TANK AIR FILTER	12.11	
1.00	D-4038	HANDLES	19.00 1,195.00	
1.00	452501121201099	WHEEL ASSEMBLY 11 1/4x25		
4.00	20109	SEAL SMALL BORE	53.00	
1.00	93924INV	MATERIAL FOR BOOM MOD	75.50	
*****	*********** Thank You ***	*********** We Believe that quality workmanship, will protect your Investment and	your Labor	22,519

************ Thank You **********	We Believe that quality workmanship, will protect your Investment and your	Labor	22,519.21
A	family.***Thank You for your Business and Come Again!***	Parts	27,852.17
		Inspection	0.00
	I hereby authorize you to perform the above repair work including	Towing	0.00
	materials may be required to repair the vehicle, and further such repairs shall not be performed until after I have authorized them either in writing or verbally. You and your employees are authorized to operate the	Sublet	0.00
Service Recommendations		Shop Charge	0.00
New engine installed at 2408.7hrs Rebuilt engine from america diesel		Subtotal	50,371.38
	vehicle on streets, highways or elsewhere at my risk for the purpose of		
	test inspection and delivery. It is understood and agreed the repair facility is not respnsible for any loss or damage to vehicle.	H.S.T.	0.00
		Amount Paid	0.00
	XReceived By	Total Due	50,371.38

Invoice Date: 01/10/2014

Invoice #

16675

Vin# Model

Plate

Miles

: 2933 Yr/Make : 1988 PETTIBONE

: 360 speedswing unit 16675

Writer Date Motor : Detroit

: Marc L : 01/30/2008

Phonel Phone2

Ext.

: HSL16675

Un

14 df	. 1.	6675
rit#	. 11	6675

Motor Hours: 2408.7

Quantity	Part Number / Tech	Description	Parts	Labor
1.00	94088NV	MATERIAL FOR REPAIRS DOOR	10.00	
1.00	B47-07631-000	AXLE SHAFT	1,118.50	
1.00	20109	SEAL	13.25	
1.00	P550936	FILTER FUEL	7.38	
4.00	G60499-0808	ADAPTER 8MJ-8MP90	10.08	
1.00	860008192INV	TIRE REPLACEMENT	684.25	
4.00	G25170-0606	6G-6FJX FITTING	20.36	
1.00	P550936	FILTER FUEL	7.00	
1.00	P550928	SECONDARY FUEL FILTER	9.15	
1.00	017716INV	SHIP ENGINE TO MIDWEST DIESEL	533.00	
8.00	8G2	HOSE #8	27.92	
10.00	6G2	HOSE #6	23.80	
6.00	G60350-1616	ADAPT 16MJ-16MJ	92.58	
8.00	G25170-0808	FITTING 8G8FJX	59.60	
4.00	G25179-0808	8G-8FJX90S	65.88	
2.00	52488	SEAL PETTIBONE WHEEL END	168.20	
2.00	52488	SEAL PETTIBONE WHEEL END	100.60	
1.00	2442465INV	SEAL AND SLEEVE	143.20	
4.00	G25170-0810	FITTINGS FEMALE 10JIC TO8 HOSE	27.36	
1.00	78939249-001	FEDEX BROKERAGE	52.00	
1.00	Q000002990INV	RADIATOR RECORE	1,400.00	
1.00	LTG12183	CONVEX 8" MIRROR	19.72	
1.00	T224	FILTER TURBO 2000	129.55	
10.00	4G2	HOSE #4 HYD 2 WIRE	19.00	
4.00	G25170-0404	FITTING 4G- 4FJX	20.92	
1.00	415645	OIL SEAL	44.15	
1.00	CN1017108	HY RAIL GUARD RIGHT SIDE	199.98	
2.00	CN1017106	HY RAIL QUARD LEFT SIDE	399.96	
8.00	80W90	Gear Lube	25.60	
3.00	1	OIL SEAL	132.45	
10.00	6G2	HOSE #6	23.80	
1.00	00425854INV	BROKERAGE CHARGES	68.00	

**************************************	We Believe that quality workmanship, will protect your Investment and your family.***Thank You for your Business and Come Again!***	Labor Parts	22,519.21 27,852.17
		Inspection	0.00
	I hereby authorize you to perform the above repair work including	Towing	0.00
	necessary parts and materials set forth. Additional labor, parts or materials may be required to repair the vehicle, and further such repairs shall not be performed until after I have authorized them either in writing or verbally. You and your employees are authorized to operate the vehicle on streets, highways or elsewhere at my risk for the purpose of	Sublet	0.00
Service Recommendations		Shop Charge	0.00
New engine installed at 2408.7hrs Rebuilt engine from america diesel		Subtotal	50,371.38
	test inspection and delivery. It is understood and agreed the repair facility is not respnsible for any loss or damage to vehicle.	H.S.T.	0.00
	racinty is not respission for any loss of damage to veniors.	Amount Paid	0.00
	XReceived By	Total Due	50,371.38

Invoice Date: 01/10/2014

Invoice #

16675

Vin# Model

Yr/Make : 1988 PETTIBONE

: 2933

: 360 speedswing unit 16675

Motor Hours: 2408.7 Writer : Marc L Date : Detroit

: 01/30/2008

: 16675

Phone1		Plate	: HSL16675	Motor	:
Phone2	Ext.	Miles	:	Unit #	:

Quantity	Part Number / Tech	Description	Parts	Labor
15.00	8G2	HOSE #8	52.35	
12.00	6G2	HOSE #6	28.56	
4.00	G25179-0808	8G-8FJX90S	65.88	
4.00	G25170-0608	6G-8FJX FITTING	23.00	
2.00	6G2	HOSE #6	4.76	
16.00	15W40	15W40 MOTOR OIL	40.96	
6.00	101C	ANTIFREEZE - GREEN	110.34	
1.00	05430226INV	LOCK VALVES	313.16	
2.00	G25175-0606	COUPLING 6GE-6FJX45M	26.66	
4.00	G60473-0808	ADAPTOR 8MJ-8FJX-8MJ	16.72	
4.00	G60420-0608	ADAPTOR 6MJ-8FJ	5.60	
4.00	G25179-0606	FITTING 90' FEMALE	69.96	
2.00	G25174-0808	COUPLING 8G-8FJX45S	35.90	
8.00	G60312-0808	ADAPTOR 8MB-8MJ90	19.84	
20.00	8G2	HOSE #8	69.80	
10.00	6G2	HOSE #6	23.80	
1.00	KN286538X	TF501 COMPRESSOR LEFT MNT	416.29	
10.00	Dexron111	Trans Fluid	31.00	
1.00	1	TF501 COMPRESSOR RIGHT MNT	456.79	
1	P148342	CLAMP-T	6.30	
i	P148343	CLAMP-T	6.34	
1.00		TEMP SENDER	36.84	
1.00		HTR SWITCH/TEMP SWITCH	43.60	
2.00		T-CLAMP	15.44	
1.00	1	WIX	0.00	
3.00		15W40 M0TOR OIL	7.98	
1.00		GRAB HANDLE	12.90	
1.00	1	HYD FILTER	48.25	
1.00	1	FOOT VALVE	77.22	
1.00	1	GAUGES AND SENDING UNITS	189.72	
1.00		TRANS PRESSURE GAUGE	99.64	
1.00		TRANS PRESS SENDING UNIT	77.16	

*********** Thank You *********	We Believe that quality workmanship, will protect your Investment and your	Labor	22,519.21
A NUMBER OF STREET	family.***Thank You for your Business and Come Again!***	Parts	27,852.17
		Inspection	0.00
	I hereby authorize you to perform the above repair work including	Towing	0.00
	necessary parts and materials set forth. Additional labor, parts or	Sublet	0.00
Service Recommendations	materials may be required to repair the vehicle, and further such repairs shall not be performed until after I have authorized them either in writing	Shop Charge	0.00
New engine installed at 2408.7hrs	or verbally. You and your employees are authorized to operate the	Subtotal	50,371.38
Rebuilt engine from america diesel	vehicle on streets, highways or elsewhere at my risk for the purpose of		
	test inspection and delivery. It is understood and agreed the repair facility is not respnsible for any loss or damage to vehicle.	H.S.T.	0.00
	lacinty is not respisible to any ross of damage to volice.	Amount Paid	0.00
	XReceived By	Total Due	50,371.38

16675 Invoice # Invoice Date: 01/10/2014 PO# Motor Hours: 2408.7 : 2933 Writer : Marc L Yr/Make: 1988 PETTIBONE : 01/30/2008 : 360 speedswing unit 16675 Date Model : HSL16675 Motor : Detroit Plate Phone1 Unit# : 16675 Miles Phone2 Ext. Labor Parts Description Quantity Part Number / Tech 23.14 oil filter 2.00 P550388 3,317.00 6071 inv REPAIR CYLINDERS 1.00 10.24.12 FILL TRANSMISSION TO PROPER LEVEL AND 60.00 Eric CHECK PLUGS AND HOSES FOR LEAKS 80.00 10.26.12 REPLACE REAR GUSSET DERICK L. 40.00 08.07.12 LABOUR Eric 40.00 08.07.12 WORK ON UNIT Eric 80.00 08.10.12 INSTALL COMPRESSOR LINES AND FITTINGS Eric 40.00 11.11.10 INSTALLED STARTER AND RECONNECTED Eric WIRING 100.00 11.08.10 CHANGED BOTH HYDRAULIC FILTERS ON Eric BOTTOM OF HYDRAULIC TANK. REMOVED THE REST OF BELTS ON FRONT OF THE ENGINE WHICH NEED REPLACEMENT. CRACKED AND STRETCHED. INSTALLED AIR LINES ON BACK OF MACHINE FOR RAILCARS 280.00 03.03.08 ASSIST CARL Bill Sto. 332.50 03.10.08 WELDING REPAIRS TO SPEED SWING Marcel 315.00 03.10.08 INSTALL ESPAR CAB HEATER Carl 300.00 07.30.12 LOCK VALVE INSTALLATION Eric 260.00 01.11.11WORK ON AXLE ASSY Paul Riche 20.00 01.11.11 FAB HOLD DOWN CLIP FOR RAD DERICK L. 20.00 10.23.12 TIGHTEN FILTER HOUSING Eric 90.00 03.24.08 Meals @ \$45.00 day per technician Mike Weibe 20.00 03.27.11 SPEED SWING BOOKS Rick P. 105.00 02.29.08 WORK ON SPEEDSWING Carl 367.50 03.05.08 REPAIR ON UNIT AND CHECK Carl 210.00 03,05.08 WELD ON UNIT Marcel 157.50 03.06.08 WELDING ON BOOM UPPER SECTION Marcel 175.00 04.02.08 INSTALL CENTER POST Ritchie C. 157.50 03.12.08 WORK WITH MARCEL ON HYRAIL GEAR Carl 40.00 10.18.12 INSTALL BOOM-LINK-PINS AND GREASE DERICK L. Labor 22,519.21 We Believe that quality workmanship, will protect your Investment and your ************** Thank You ********** family.***Thank You for your Business and Come Again!*** Parts 27,852.17 Inspection 0.00 0.00 Towing I hereby authorize you to perform the above repair work including necessary parts and materials set forth. Additional labor, parts or Sublet 0.00 materials may be required to repair the vehicle, and further such repairs Service Recommendations Shop Charge 0.00 shall not be performed until after I have authorized them either in writing New engine installed at 2408.7hrs or verbally. You and your employees are authorized to operate the Subtotal 50,371.38 Rebuilt engine from america diesel

vehicle on streets, highways or elsewhere at my risk for the purpose of test inspection and delivery. It is understood and agreed the repair

Received By

facility is not respnsible for any loss or damage to vehicle.

H.S.T.

Amount Paid

Total Due

0.00

0.00

50,371.38

16675 Invoice # Invoice Date: 01/10/2014 PO# Motor Hours: 2408.7 : 2933 Vin# Writer : Marc L Yr/Make: 1988 PETTIBONE : 01/30/2008 : 360 speedswing unit 16675 Date Model : Detroit Motor : HSL16675 Plate Phone1 Unit# : 16675 Miles Ext. Phone2 Labor Parts Description Part Number / Tech Quantity 320.00 10.22.12 REPLACE AIR BRAKE VALVE REPLACE Eric HYDRAULIC AND TRANSMISSION FILTER 320.00 12.15.10 HARD FACE PINEAPPLE AND FAB WELD RINGS DERICK L. FAB PLATE FOR BOOM STIFFNER. PICKUP, DROPPOFF MATERIAL FOR JOB 87.50 03.17.08 WORK ON CLAM Carl 70.00 03.11.08 WORK ON TRAIN VALVE, REPLACE BROKEN Jack J HANDLE 180.00 01.13.11 INSTALL STOLEN PARTS TO OTHER 360. INSTALL Paul Riche VALVE BODY 35.00 03.08.08 CLEAN CAB AND WINDOW Ray G. 35.00 03.03.08 CHECK UNIT Daryl H. 280.00 03.04.08 REPAIR AS PER LIST Marcel 03.04.08 INSTALL FUEL TANK FOR INTERIOR HEATER 280.00 Carl 297.50 03.08.08 WELDING ON BOOM SECTION Marcel 245.00 03.07.08 WELDING ON BOOM Marcel 0.00 10.29.12 REMOVE DAMAGED HYRAIL GUARDS, REMOVE Harold F AND CLEEAN STEERING SOLENOIDS, REMOVE STERING CYLINDERS-BYPASSING, REMOVE TOTE BOOM CYLINDER, SERVICE DEAUTZ ENGINE 40.00 10.29.12 CUT AND INSTALL GUARDS DERICK L. 80.00 11.19.12 INSTALL HYDRAULIC CYLINDER Greg B 210.00 03.06.08 WORK ON INSTALLING INTERIOR HEATER Mike Arm. 40.00 01.07.12 REPLACE FUEL FILTERS-AIR UP TANK.ATTEMPT Rick P. TO START UNIT 87.50 03.12.08 WORK ON ELECTRICAL FOR BOOM Carl 70.00 03.11.08 FINISH REPAIRS AND CHANGE CABLE ON Eric WELDER, CHANGE END PLUG TO FEMALE 157.50 03.07.08 INSTALL CAB HEATER Mike Arm. 40.00 12.22.10 PAINT HIRAIL, WELD INSPECTION DERICK L. 140.00 01.12.11 VALVE BODY PREP FOR INSTALLATION Paul Riche 192.50 03.06.08 WORK ON BRAKES AND FUEL TANK Jack J 22,519.21 Labor We Believe that quality workmanship, will protect your Investment and your ************ Thank You ********** family.***Thank You for your Business and Come Again!*** Parts 27,852,17 0.00 Inspection Towing 0.00 I hereby authorize you to perform the above repair work including necessary parts and materials set forth. Additional labor, parts or Sublet 0.00 materials may be required to repair the vehicle, and further such repairs Service Recommendations Shop Charge 0.00shall not be performed until after I have authorized them either in writing New engine installed at 2408.7hrs Subtotal 50,371.38 or verbally. You and your employees are authorized to operate the Rebuilt engine from america diesel vehicle on streets, highways or elsewhere at my risk for the purpose of test inspection and delivery. It is understood and agreed the repair H.S.T. 0.00 facility is not respnsible for any loss or damage to vehicle. Amount Paid 0.00

Received By

50,371.38

Total Due

16675 Invoice # Invoice Date: 01/10/2014 PO# Motor Hours: 2408.7 : 2933 Vin# Writer : Marc L Yr/Make: 1988 PETTIBONE : 01/30/2008 : 360 speedswing unit 16675 Date Model : Detroit Motor : HSL16675 Plate Phone1 Unit# : 16675 Miles Ext. Phone2 Labor Parts Description Part Number / Tech Quantity 380.00 03.24.08 FLOAT SUDBURY TO TORONTO Mike Weibe 400.00 03.25.08 TORONTO TO BARRIE Mike Weibe 260.00 03.26.08 BARRIE TO SUDBURY Mike Weibe 169.21 LODGING 03.24.08 TO 03.25.08 Mike Weibe 40.00 02/03/09 CHECK FOR LEAKS Bill Sto. 105.00 03.10.08 PAINT STEPS, HAND GRIPS AND GUARDS Mike Weibe 105.00 03.11.08 FINISH CLEANING AND PAINTING Mike Weibe 03.12.06 DEL UNIT TO TORONTO TTR SITE AND RETURN 420.00 Mike Weibe TO SHOP 80.00 09.14.12 NSTALL ENGINE COVERS Nick C 160.00 05.25.12 PREP ENGINE FOR SHIPPING Eric 300.00 09.10.12 ENGINE INSTALLATION AND HOOKUP Eric 20.00 09.12.12 CHECK AND FILL HUBS Nick C 300.00 09.12.12 HOOK UP ACCESSORIES Eric 60.00 09.10.12 INSTALL RADIATOR AND SHROUD Eric 80.00 05.28.12 REMOVE HUB AND CLEAN PARTS DERICK L. 80.00 12.14.10 STRAIGHTEN CAB DERICK L. 80.00 11.19.12 INSTALL HYDRAULIC CYLINDERS Jamie C 300.00 06.14.12 INSTALL INNER AND OUTER PLANETARY Eric SEALS, INSTALL PLANETARY AND TORQUE BEARINGS, INSTALL SEAL AND SLEEVE ON BRAKE ROTOR, FREEUP BRAKE CALIPER AND INSTAL ROTOR, REPAIR BOOM SWITCH WIRING 160.00 10.25.12 INSPECTION Harold F 160.00 01.10.11 WORK ON AXLE DERICK L. 12.22.10 REMOVED BOTH REAR PINEAPPLE WHEELS 20.00 Eric 52.50 04.02.08 ASSIST CLAMP Ritchie C. 1,100.00 WORK DONE ON UNIT MOVED FROM 21702 Dave N. 220.00 REMOVED BROKEN AXLE RIGHT FRONT AXLE Eric 20.00 03.19.10 INSTALLED DOOR HANDLE ON PASSENGER REAR Eric DOOR, TESTED DOOR. INSTALLED LOAD CHART CABLE TO LOAD CHART BOX. 22,519.21 Labor We Believe that quality workmanship, will protect your Investment and your *********** Thank You ********* family.***Thank You for your Business and Come Again!*** 27,852.17 Parts 0.00 Inspection Towing 0.00 I hereby authorize you to perform the above repair work including necessary parts and materials set forth. Additional labor, parts or Sublet 0.00 materials may be required to repair the vehicle, and further such repairs Service Recommendations Shop Charge 0.00 shall not be performed until after I have authorized them either in writing New engine installed at 2408.7hrs Subtotal 50.371.38 or verbally. You and your employees are authorized to operate the Rebuilt engine from america diesel vehicle on streets, highways or elsewhere at my risk for the purpose of test inspection and delivery. It is understood and agreed the repair H.S.T. 0.00 facility is not respnsible for any loss or damage to vehicle. 0.00 Amount Paid

Received By

50,371.38

Total Due

Invoice # 16675 Invoice Date: 01/10/2014 PO# Motor Hours: 2408.7 : 2933 Vin# Writer : Marc L : 1988 PETTIBONE Yr/Make Date : 01/30/2008 Model : 360 speedswing unit 16675 : Detroit : HSL16675 Motor Plate Phone1 Unit# : 16675 Miles Ext. Phone2 Labor Parts Description Part Number / Tech Quantity 120.00 05.24.12 REASSAMBLE INJECTORS AND ROCKERS-READY Eric ENGINE FOR SHIPPING 08.13.12 PRESSURE WASH UNIT AND PREP FOR ENGINE 180.00 DERICK L. INSTALLATION 280.00 12.29.10 INSTALL PINEAPPLES, FAB, WELD RINGS & DERICK L. INSTALL, REMOVE OLD PIN, FAB NEW ONE. INSTALL PULL STUDS IN FRONT 120.00 01.05.12 ATTEMPT TO START AND MOVE UNIT Rick P. 40.00 Jamie C 10.29.12 LABOR 60.00 03.28.11 START TIRES Rick P. 280.00 03.07.08 SERVICE GENERATOR ASSIST CARL Jack J 40.00 05.25.12 PREP ENGINE FOR POWER WASHING Nick C 20.00 CHECK UNIT OVER Eric 120.00 03.03.10 CHANGED ALL FUEL LINES, REMOVED GAS TANK Eric FLUSHED OUT. REPLACED FUEL FILTER. REPAIRED WIRES ON FUEL SOLENOID. GET ENGINE RUNNING OUT, NEEDS A NEW LIFT PUMP, LEAKING FUEL EVERYWHERE. 87.50 02,29.08 WELDING REPAIRS ON CRACKS Marcel 03.08.08 WORK ON INTERIOR AND ASSIST MARCEL WITH 315.00 Ritchie C. REPAIR ON BOOM AND MOUNTING HY RAIL. 280.00 03.07.08 CHECK ALL OIL LEVELS, CHANGED OIL IN Carl PLANETARY,S AND REFILL, CHANGE OIL IN TRANSMISSION. 315.00 03.03.08 REPAIRS AS PER LIST. REPLACED Carl FILTERS, REMOVED GRAPPEL, REPAIR COOLING MOUNT, SERVICE UNIT 52.50 03.03.08 ASSIST WITH LIST Mike Arm. 280.00 03.03.08 REPAIR ON UNIT BOOM CLEAN AND WELD Marcel CRACKEDS AND FRONT FRAME, REMOVED WORN **BUSHING IN BOOM** 680.00 03.11.08 WELDING ON BOOM Marcel 22,519.21 We Believe that quality workmanship, will protect your Investment and your Labor ************* Thank You ********* family.***Thank You for your Business and Come Again!*** Parts 27,852.17 0.00 Inspection 0.00 Towing I hereby authorize you to perform the above repair work including necessary parts and materials set forth. Additional labor, parts or Sublet 0.00 materials may be required to repair the vehicle, and further such repairs Service Recommendations Shop Charge 0.00 shall not be performed until after I have authorized them either in writing New engine installed at 2408.7hrs Subtotal 50,371.38 or verbally. You and your employees are authorized to operate the Rebuilt engine from america diesel vehicle on streets, highways or elsewhere at my risk for the purpose of

test inspection and delivery. It is understood and agreed the repair

Received By

facility is not respnsible for any loss or damage to vehicle.

H.S.T.

Amount Paid

Total Due

0.00

0.00

50,371.38

16675 Invoice # Invoice Date: 01/10/2014 PO# Motor Hours: 2408.7 : 2933 Writer : Marc L Yr/Make : 1988 PETTIBONE : 01/30/2008 : 360 speedswing unit 16675 Date Model Motor Detroit Plate : HSL16675 Phonel Unit# : 16675 Miles Phone2 Ext. Labor Parts Description Ouantity Part Number / Tech 280.00 11.05.10 RECONNECTED AIRLINES FOR RAIL CARTS, Eric CHANGED ENGINE OIL, FILTER, BOTH FUEL FILTERS & ARI FILTER. CHANGED COOLANT FILTER. REMOVED BROKEN SOLENOID IN THE FRONT FOR HI-RAIL. TIGHTENED UP LOOSE HOSES UNDER MACHINE. REROUTED WIRING HARNESS UNDERNEATH MACHINE & TIED UP PROPERLY. REMOVED STARTER. NEED TO BE SENT OUT FOR REPAIR. REMOVED ALTERNATOR BELTS. 40.00 03.04.10 REPLACED FUEL SUPPLY PUMP, BLED ALL FUEL Eric LINES. RAN ENGINE & CHECKED FOR LEAKS. 120.00 03.04.10 FAB & INSTLL NEW BOOK BOLT. WELDING Phil St. J REPAIRS TO FRAME (2 LOCATIONS) FAB STEERING LOCKING BAR. HELP CAR WITH MECHANICAL WORK 40.00 11.24.10 WORK ON HYDRAULIC HOSES Eric 60.00 08.08.12 INSTALL COMPRESSORS ON ENGINE Nick C 05.29.12 REPAIRS AS PER LIST, REMOVE DRIVESHAFT AND 300.00 Eric PARK BRAKE ASSEMBLY TO REPLACE PINION SEAL, REPLACE AIR DRYER AND CONVEX MIRROR 140.00 05.30.12 REPAIRS AS PER LIST Eric 80.00 11.16.12 INSTALL STEERING CYLINDERS Kyle K 60.00 05.25.12 REFIT ENGINE STAND Richard L 120.00 05.18.11 CHECK UNIT OVER AND WASH Eric 01.09.12 BRING UNIT INTO SHOP-BEGIN RETURN RETURN 60.00 Eric CHECKLIST 300.00 08.08.12 REMOVE ENGINE FROM CRATE AND INSTALL Eric **COMPONENTS** 260.00 05.18.12 DICONNECT WIRING HARNESS AND HYDRAULIC Eric LINES, DRAINED COOLANT AND REMOVE ENGINE FROM MACHINE 20.00 05.24.12 DRAIN OIL AND BUILD SHIPPING CRATE Eric 300.00 08.09.12 INSTALL ACCESSORY COMPONENTS ON ENGINE Eric 22,519.21 We Believe that quality workmanship, will protect your Investment and your Labor *********** Thank You ********* family *** Thank You for your Business and Come Again! ** Parts 27,852.17 Inspection 0.00 0.00 Towing I hereby authorize you to perform the above repair work including necessary parts and materials set forth. Additional labor, parts or 0.00 Sublet materials may be required to repair the vehicle, and further such repairs Service Recommendations Shop Charge 0.00shall not be performed until after I have authorized them either in writing New engine installed at 2408.7hrs or verbally. You and your employees are authorized to operate the Subtotal 50,371.38 Rebuilt engine from america diesel

vehicle on streets, highways or elsewhere at my risk for the purpose of test inspection and delivery. It is understood and agreed the repair

Received By

facility is not respnsible for any loss or damage to vehicle.

H.S.T.

Amount Paid

Total Due

0.00

0.00

50,371.38

Invoice Date: 01/10/2014

Invoice #

16675

Yr/Make Model

Plate

Miles

: 2933 : 1988 PETTIBONE

: 360 speedswing unit 16675

Motor Hours: Writer Date

: Marc L : 01/30/2008

2408.7

Phone1 Phone2

Ext.

: HSL16675 ;

Motor : Detroit Unit#

: 16675

Quantity	Part Number / Tech		Description	P	arts	Labor
	Eric	10.17.12 INST	ALL TRANSMISSION PRESSURE GAUGE-FILL			200.00
			PLANETARY LEVELS			
	Eric	10.26.12 REM	OVE FRONT STEERING VALVE-CLEAN AND			140.00
		REASSEMBI				
	Paul Riche		AN PARTS FOR AXLE FOR REASSEMBLY			260.00
	Eric	10.24.12 DRA	IN OIL AND WATER FROM HYDRAULIC TANK			160.00
		AND FILL,				
			FLUID LEVELS AND ADJUST-TEST BRAKES			
	Rick P.	11.05.10 MAI	DE NEW BRACKET TO HOLD NEW AIR			80.00
		FITTINGS, D	RILLED HOLES, WELD ON MACHINE			,
	Paul Riche	12.28.10 TRO	UBLESHOOT REAR HIRAIL NOT WORKING.			120.00
			COIL AND STEEL PLUNGER. PLUNGER WAS			
			O UP SOME OLD WIRING TAHT WAS NO			
		GOODTES	TED-BOTH HIRAILS NOW WORK, CLEAN UP			
	Eric	11.22.10 INST	TALL BELTS AND QUARDS,REPAIR RAD			100.00
		OVERFLOW				
	Paul Riche	12.23.10 TRO	UBLESHOOT REAR HIGH RAIL NOT			160.00
		WORKING				
	Eric		ANGED ALL BELTS ON FRONT OF ENGINE			100.00
	Eric	11.09.10 REP	AIRED WIRING GOING TO REAR TAILLIGHTS			40.00
		& SIGNAL L	IGHTS			
	DERICK L.		DOOR AND WINDOW			120.00
	DERICK L.	12.30.10 FAE	RICATED BOOM PLATE.RESURFACE			240.00
		PINAPPLE,	•			
	Paul Riche	12.30.10 CLI	EAN UP OIL LEAKS AND FLOOR			40.00
	Eric	Motor is core	only to be sent out for rebuild			1,000.00
	Marc L	05.17.12 CH	ECK ENGINE			300.00
	Jamie C	04.18.12 WC	RK ON UNIT			40.00
	Eric	05.17.12 REN	MOVE HOOD TO ACCESS ENGINE, REMOVE			160.00
		ROCKER CO	OVER AND ARMS REMOVE INJECTORS			
		PERFORM A	COMPRESSION TEST, MOTOR REQUIRES			
		REPLACING	à			
. داد داد چې وي		******	We Believe that quality workmanship, will protect your Investment and	l your	Labor	22,519.2
************* Thank You ***********			family ***Thank You for your Rusiness and Come Again!***	-	Domto	27 052 12

	-
Service Recommendations	
New engine installed at 2408.7hrs	
Rebuilt engine from america diesel	
· ·	

I hereby authorize you to perform the above repair work including necessary parts and materials set forth. Additional labor, parts or materials may be required to repair the vehicle, and further such repairs shall not be performed until after I have authorized them either in writing or verbally. You and your employees are authorized to operate the vehicle on streets, highways or elsewhere at my risk for the purpose of test inspection and delivery. It is understood and agreed the repair

Received By

facility is not respnsible for any loss or damage to vehicle.

family ***Thank You for your Business and Come Again!***

Parts	27,852.17	
Inspection	0.00	
Towing	0.00	
Sublet	0.00	
Shop Charge	0.00	
Subtotal	50,371.38	
H.S.T.	0.00	
Amount Paid	0.00	
Total Due	50,371.38	

16675 Invoice # Invoice Date: 01/10/2014 PO# Motor Hours: 2408.7 : 2933 Vin# Yr/Make: 1988 PETTIBONE Writer : Marc L Date : 01/30/2008 : 360 speedswing unit 16675 Model Motor : Detroit : HSL16675 Plate Phonel : 16675 Unit# Miles Ext. Phone2 Parts Labor Description Part Number / Tech Quantity 05.22.12 CHECK MACHINE AS PER LIST, REMOVE 300.00 Eric RADIATOR AND SHROUD PLUG AND CAP TRANSMISSION COOLER LINES, SEE CHECKLIST FOR DEFECTS 240.00 05.25.12 WENT THRU CHECKLIST, INSTALL FRONT Eric PLANETARY COVER AND SEALED, REPAIR WIRING FOR GAUGE CLUSTER, REMOVED LEAING REAR PLANETARY, CLEANED BRAKES 160.00 05.29.12 REPAIR CRACKEDED SHROUD AND REPAINT Richard L 260.00 07.31.12 MOUNT 2 LOCK VALVES AND RUN HYDRAULIC Eric HOSES 08.09.12 INSTALL ENGINE ACCESSORY COMPONENTS 40.00 Nick C 40.00 08.17.12 MAKE AND INSTALL HOSE FOR RIGHT REAR Eric LOCK VALVE 280.00 09.14.12 CHECK AND TOP UP EQUIPMENT Eric FLUIDS.INSTALL COVERS START ENGINE AND CHECKOVER-MAKE UP HOSES FOR LOCK VALVES 240.00 09.11.12 ENGINE INSTALLATION Kyle K 80.00 09.13.12 CHECK AND FILL ENGINE FLUIDS Nick C 160.00 09.14.12 MAKE COOLANT LINES AND INSTALL-ENGINE Eric HOOKUP AND STARTUP 20.00 09.26.12 REPLACE WATER TEMP GAUGE AND SENDER Eric 200.00 09.25.12 INSTALL HYRAIL GUARDS AND MODIFY TO Eric FIT.INSTALL GAUGES 200.00 09.19.12 CONNECT AND ADJUST FRONT BRAKES, REMOVE Eric ENGINE AND TRANSMISSION TEMPERATURE GAUGES 09.26.12 INSPECT HYRAIL COVER INSTALLATION AND 20.00 DERICK L. CHECK FOR CRACKED WELDS

******************************	We Believe that quality workmanship, will protect your Investment and your family.***Thank You for your Business and Come Again!***	Labor Parts	22,519.21 27,852.17
•	I hereby authorize you to perform the above repair work including necessary parts and materials set forth. Additional labor, parts or	Inspection Towing Sublet	0.00 0.00 0.00
Service Recommendations New engine installed at 2408.7hrs Rebuilt engine from america diesel	materials may be required to repair the vehicle, and further such repairs shall not be performed until after I have authorized them either in writing or verbally. You and your employees are authorized to operate the vehicle on streets, highways or elsewhere at my risk for the purpose of	Shop Charge Subtotal	0.00 0.00 50,371.38
		H.S.T. Amount Paid	0.00
	XReceived By	Total Due	50,371.38