

Condition Report March 22, 2019, 8:26 a.m.

Truck Info

Make	Shuttle wagon
Model	NVX6030
Model Year	
Serial Number	603014066

Description	Status
Key Hours	3777:4
Drive Hours	Engine hours 3777.4
Lift Hours	Not Applicable
Volts	24
Fuel Type	Diesel
Stages	Not Applicable
Collapsed Height	Not Applicable
Raised Height	Not Applicable



Category	Description	Status	Notes	Resolution
Tires	Tire Type	Pneumatic		\$0 (All tires has some dry rot)
Hydrulaics	Functions	Not Applicable		\$1200 (Lift cylinder for rail drive on left front damaged)
Attachment	Attachment Type	Other		
Forks	Fork Length	Not Applicable		
Appearance	Overall	Acceptable		
Attachments / Forks	Condition	Acceptable		
Brakes	Parking Brake	Acceptable		
	Brake System	Acceptable		
Carriage	Frame	Acceptable		
	Rollers	Acceptable		
Covers	Overall	Acceptable		
	Dash	Acceptable		
	Fenders	Acceptable		
	Hood	Acceptable		
Drive Axle	Overall	Acceptable		
Drive Gear(s)	Overall	Acceptable		
Electric System	Battery	Acceptable		
	Display	Good		
	Ignition	Acceptable		
Frame	Overall	Acceptable - No Dents		
Lift Cylinders	Overall	Good		
Lights	Head Lights	Working		
	Strobe Lights	Working		
Load Back Rest	Overall	Acceptable		
Pump / Motor	Hoses	Leaking		\$3500 (Fan drive pump for radiator cooling leaking)
	Levers	Good		
	Overall	Acceptable		
Safety	Alarms & Horn	Good		
	Overhead Guard	Acceptable	Cab and drive area in good shape	
	Pedals & Floormat	Acceptable		
	Cushion & Seatbelt	Good		

Category	Description	Status	Notes	Resolution
Tilt Cylinders	Overall	Other		
Tires	Drive Tire %	65+		
	Drive Tire Cond.	Acceptable		
	Steer Drive %	Not Applicable		
	Steer Tire Cond.	Acceptable		
Upright	Chains	Acceptable		
	Mast	Acceptable		
Total Estimated Repair Cost				\$4700



[Full Image](#)



[Full Image](#)



[Full Image](#)



[Full Image](#)



[Full Image](#)